



NEW NO CORE PROFLEET NO_x SENSORS

What to Know about NO_x Sensors:

Quick Facts


- Life Expectancy of 3 months
- Lasts roughly 50,000 to 60,000 miles
 - Can easily fail before this

What Causes Failure?

- Soot Buildup
- ECU Water Intrusion
- Damage to the cable

What Happens If You Don't Replace The Sensor?

- First – Motor may start running rough and cause fuel consumption to severely increase.
- Next – Motor may go into limp mode.
 - A/C will shut off
 - Speed will be reduced
- Lastly – The truck may break down and stop running all together.



About ProFleet NO_x Circuit Board

- Waterproof Anti-Corrosion Potting Material
- No Risk of Water Leakage
- Probe is Soldered to Improve Electrical Connection
- Competitor Lacks Welding Treatment Causing Signal Abnormalities
- Clamp Protection
- Gets Rid of Wire Break
- Limits Chances of Water Damage



FYDA FREIGHTLINER

Where "The Customer is First"

WHILE SUPPLIES LAST!



NEW NO CORE PROFLEET NO_x SENSORS

Cross Reference Sample

- Replacement sensors for exhaust systems
- OEM or OEM exact
- Easy Installation



OEM #	PROFLEET #	POSITION	APPLICATION
2894939RX, A034X846, 2894943	PRO20203001	OUTLET	2010-2012 ISX 12, ISX 15, ISB 6.7L
2894945, 5293295	PRO20203002	OUTLET	2013-2019 ISB 6.7L, ISX 15, ISX 11.9
4326869RX, A2C95993800-01, A045S164, PACCAR#1954666PRX	PRO20203003	OUTLET	2013-2019 ISB 6.7L
4326873RX, A045S170, 4326873, A2C95991800-01	PRO20203004	INLET	2011-2018 ISX 12, ISX 15, ISL
4326874, A045S171, A2C95991400-01	PRO20203005	OUTLET	2011-2018 ISX 15, ISX 11.9
3687334RX, 2894941	PRO20203007	INLET	2008-2010 ISX 12, ISX 15
4326872RX, A045S169, 4326872, A2C95992000-01	PRO20203008	OUTLET	2011-2018 ISX 12, ISX 15
2894944	PRO20203014	OUTLET	2010-2012 ISX 12, ISX 15, ISB 6.7L
4326870RX, A045S167, 3687930	PRO20203015	INLET	2013-2015 ISX 12, ISX 15

859-379-7330 **513-772-7171** **614-851-0002** **740-487-1730** **330-797-0224** **724-514-2055** **814-786-8009**
 WALTON, KY CINCINNATI, OH COLUMBUS, OH ZANESVILLE, OH YOUNGSTOWN, OH PITTSBURGH, PA BARKEYVILLE, PA

www.fydafreightliner.com